

MASTR II MAINTENANCE MANUAL

138-174 MHz DUAL FRONT END (WITH NOISE BLANKER)

OPTION 9201 (matching IF Freq.) (Non-NB version is LBI-30024)

OPTION 9202 (non-matching IF Freq.)




TABLE OF CONTENTS

SPECIFICATIONS	ii
COMBINATION NOMENCLATURE	ii
DESCRIPTION AND MAINTENANCE	LBI30112 (DF1110)
RF AMPLIFIER ASSEMBLY AND MIXER/IF/BLANKER BOARD	LBI 4982 (DF1107)
OSCILLATOR/MULTIPLIER BOARD	LBI 4984 (DF1106)
RF STEERING SWITCH, MIXER/IF SWITCH/2ND CONVERTER	LBI30038

SPECIFICATIONS*

SENSITIVITY

DFE 12-dB SINAD

20-dB Quieting Method

0.20 µV 0.275 μV

RECEIVER

Sensitivity degraded not more than 1 dB from standard Receiver Specifications

SELECTIVITY

EIA Two-Signal Method 20 dB Quieting Method

-100 dB -100 dB

INTERMODULATION (EIA)

-75 dB

SPURIOUS RESPONSE

-95 dB

MODULATION ACCEPTANCE

±7 kHz (narrow-band)

FREQUENCY STABILITY

5C-ICOM with EC-ICOM 5C-ICOM or EC-ICOM 2C-ICOMS

 $\pm 0.0005\%$ (-40°C to +70°C) $\pm 0.0002\%$ (0°C to +55°C) $\pm 0.0002\%$ (-40°C to +70°C)

MAXIMUM FREQUENCY SEPARATION (Multi-Frequency Units)

138-155 MHz

Full Specifications

3 dB Degradation

150.8-174 MHz

.900 MHz 1.0 MHz

50 ohms

1.60 MHz 1.80 MHz

RF INPUT IMPEDANCE

CURRENT DRAIN (TYPICAL)

Non-matching IF's - 100 mA

Matching IF's - 75 mA

* These specifications are intended primarily for the use of the serviceman. Refer to the appropriate Specification Sheet for the complete specifications.

COMBINATION NOMENCLATURE

lst Digit	2nd Digit	3rd Digit	4th Digit
Frequency Capability	Options	Frequency Range	Oscillator Stability
A 1-Freq.	Noise Blanker	56 138-155 MHz	±5 PPM (±0.0005%)
D _{2-Freq.}		66 150.8-174 MHz	±2 PPM (±0.0002%)
3-Freq.			
4-Freq.			
G 5-Freq.			
H 6-Freq.			
J 7-Freq.			

- WARNING -

Although the highest DC voltage in the MASTR II receiver is +12 Volts DC, high current may be drawn under short circuit conditions. These currents can possibly heat metal objects such as tools, rings, watchbands, etc., enough to cause burns. Be careful when working near energized circuits.

High-level RF energy in the transmitter Power Amplifier assembly can cause RF burns. KEEP AWAY FROM THESE CIRCUITS WHEN THE TRANSMITTER IS ENERGIZED!