

MASTR'II MAINTENANCE MANUAL

138-174 MHz RECEIVER




TABLE OF CONTENTS

SPECIFICATIONS	ii
DESCRIPTION AND MAINTENANCE	LBI30109 (DF1101)
RF AMPLIFIER, MIXER IF ASSEMBLY	LBI 4980 (DF1107)
OSCILLATOR/MULTIPLIER BOARD	LBI 4984 (DF1106)
IF-AUDIO & SQUELCH BOARD	LBI 4986 (DF1105)

SPECIFICATIONS*

Audio Output (to 8-ohm Speaker

12 Watts at less than 3% distortion

Sensitivity		With Pre-Ampl	Without Pre-Ampl
12-dB SINAD (EIA Method) 20-dB Quieting Method		0.175 μV 0.25 μV	0.35 μV 0.50 μV
SELECTIVITY			
EIA Two-Signal Method 20-dB Quieting Method		-95 dB	-100 dB -100 dB
Spurious Response		-95 dB	-100 dB
Intermodulation (EIA)		-80 dB	−85 d B
Frequency Stability			
5C-ICOM with EC-ICOM 5C-ICOM or EC-ICOM 2C-ICOMS		±0.0005% (-40°C to +70°C) ±0.0002% (0°C to +55°C) ±0.0002% (-40°C to +70°C)	
Modulation Acceptance		±7 kHz (narrow-band)	
Squelch Sensitivity			
Critical Squelch Maximum Squelch		0.2 μV Greater than 20 dB quieting (less than 1.5 $\mu V)$	
Maximum Frequency Separation	<u>Full</u>	Specifications	3 dB Degradation
138-155 MHz 150.8-174 MHz		.900 MHz 1.0 MHz	1.60 MHz 1.80 MHz
Frequency Response		Within +1 and -8 dB of a standard 6-dI per octave de-emphasis curve from 300 to 3000 Hz (1000-Hz reference)	

RF Input Impedance

50 ohms

- WARNING -

Although the highest DC voltage in the MASTR II receiver is +12 Volts DC, high current may be drawn under short circuit conditions. These currents can possibly heat metal objects such as tools, rings, watchbands, etc., enough to cause burns. Be careful when working near energized circuits!

 $\begin{array}{ll} \mbox{High-level RF energy in the transmitter Power Amplifier assembly can cause RF burns. KEEP AWAY FROM THESE CIRCUITS WHEN THE TRANSMITTER IS ENERGIZED!} \\ \end{array}$

^{*}These specifications are intended primarily for the use of the serviceman. Refer to the appropriate Specification Sheet for the complete specifications.