MASTR Executive II MAINTENANCE MANUAL

138-174 MHz RECEIVER

(Noise Blanker version is LBI-30056)




TABLE OF CONTENTS

SPECIFICATIONS	ii
DESCRIPTION AND MAINTENANCE	LBI30130 (DF1112)
RF ASSEMBLY AND MIXER/IF BOARD	LBI4980 (DF1107)
OSCILLATOR/MULTIPLIER	LBI30057 (DF1106)
IF-DETECTOR	LBI30049 (DF1105)

SPECIFICATIONS*

Audio Output (to 3.2 ohm Speaker)	5 Watts at 1	5 Watts at less than 5% distortion		
Sensitivity	Standard Receiver	Ultra-High Sensitivity Receiver	RCC ६ IMTS Receiver	
12 dB SINAD (EIA Method) 20 dB Quieting Method	0.35 μV 0.50 μV	0.175 μV 0.25 μV	0.5 μV 0.63 μV	
Selectivity EIA Two-Signal Method	-90 dB	-90 dB	-90 dB	
Spurious Response	-100 dB	-95 dB	-100 dB (TX Unkeyed) -85 dB (TX Keyed)	
Intermodulation (EIA)	-85 dB	-80 dB	-80 dB	
Frequency Stability	±0.0005%		±0.0005%	
Modulation Acceptance	±7 kHz		±7 kHz	
Squelch Sensitivity Fixed Squelch	4 dB SINAD			
Maximum Frequency Separation	Full Sp	ecifications	3 dB degradation	
138-155 MHz 150.8-174 MHz	0. 1.	900 MHz 0 MHz	1.60 MHz 1.80 MHz	
Frequency Response		Within +1 and -8 dB of a standard 6 dB per octave de-emphasis curve from 300 to 3000 Hz (100 Hz reference)		
RF Input Impedance	50 ohms	50 ohms		

^{*} These specifications are intended primarily for the use of the serviceman. Refer to the appropriate Specification Sheet for the complete specifications.

--- WARNING -

Although the highest DC voltage in MASTR Executive II Mobile Equipment is supplied by the vehicle battery, high currents may be drawn under short circuit conditions. These currents can possibly heat metal objects such as tools, rings, watchbands, etc., enough to cause burns. Be careful when working near energized circuits!

High-level RF energy in the transmitter Power Amplifier assembly can cause RF burns upon contact. Keep away from these circuits when the transmitter is energized!

GENERAL ELECTRIC COMPANY+ MOBILE COMMUNICATIONS DIVISION WORLD HEADQUARTERS+LYNCHBURG, VIRGINIA 24502 U.S.A.

