

for
Manual No. 68P81067C40-A
MT1000® Instruction Manual

This revision outlines changes that have occurred since the printing of the manual or previous revisions. Use this information to supplement your manual. Installation of these changes in earlier equipment is not necessary except as recommended in Motorola Service and Repair Notes (SRN's).

REVISION DETAILS**NO.: CHANGE AFFECTS:**


- 1 LOWBAND TRANSCEIVER CIRCUIT BOARD AND SCHEMATIC DIAGRAM
- 2 LOWBAND Electrical Parts List, Transceiver Board TPLF-3876-A

CHANGES:**NO.:**

- 1 On page 71, **LOWBAND TRANSCEIVER CIRCUIT BOARD AND SCHEMATIC DIAGRAM**, replace circuit boards and schematic with the new drawings provided.
- 2 On page 72, **LOWBAND Electrical Parts List, Transceiver Board**, change the following:


<u>REFERENCE SYMBOL</u>	<u>ACTION</u>	<u>MOTOROLA PART NO.</u>	<u>DESCRIPTION</u>
C137	delete	2311049A37	1 μ F

VIEWED FROM SIDE 1 (COMPONENT SIDE)



L4-CEPF-20757-A
L1-CEPF-20758-A
OL-CEPF-20758-B

VIEWED FROM SIDE 2 (SOLDER SIDE)



OL-CEPF-20761-B

