


## MASTR Executive II MAINTENANCE MANUAL

157.770-158.670 MHz, 22-WATT RCC & IMTS SYNTHESIZED TRANSMITTER



## TABLE OF CONTENTS

SPECIFICATIONS	11
DESCRIPTION AND MAINTENANCE	LBI30803 (DF3163)
POWER AMPLIFIER	LBI30054 (DF3166)

## SPECIFICATIONS\*

Power Output	22 Watts
Deviation	+/- 5 kHz
Spurious and Harmonic Emission per EIA RS152B Paragraph 4	-80 dB
Frequency Stability Standard Optional	+/-0.0005% +/-0.00025%
FM Noise	-70 dB
Audio Response (300-3000)	+1, -3 dB
Audio Distortion @1000 Hz @300-3000 Hz	less than 3% less than 5%
FCC Type Acceptance No.	KT - 173 - A

<sup>\*</sup>These specifications are intended primarily for the use of the serviceman. Refer to the appropriate Specification Sheet for the complete specifications.

## ---- WARNING -

Although the highest DC voltage supplied to the transmitter is  $\pm 12~\mathrm{VDC}$ , high currents may be drawn under short circuit conditions. These currents can possibly heat metal objects such as tools, rings, watchbands, etc., enough to cause burns. Be careful when working near energized circuits!

High-level RF energy in the transmitter Power Amplifier assembly can cause RF burns upon contact. Keep away from these circuits when the transmitter is energized!

GENERAL ELECTRIC COMPANY+ MOBILE COMMUNICATIONS DIVISION WORLD HEADQUARTERS+LYNCHBURG, VIRGINIA 24502 U.S.A.

