



Center hole was factory drilled. On my antenna network, it should have been moved Southwest about half the diameter of the hole.

I recommend that you print the template, cut it out with a razor blade, punch the holes with a hole-punch, and then test the fit on your antenna network BEFORE drilling any holes.

- de WM4B