

GENERAL:

This revision outlines changes that have occurred since the printing of your instruction manual. Use this information to update your instruction manual.

INSTRUCTION MANUAL AFFECTED:

68-80101W58-A Radius VHF/UHF/800 MHz Two-Way FM Radio Service Manual

REVISION DETAILS:

The information in this manual for servicing the Radius M206 and M214 models is directly applicable to servicing the Radius models M208 (8 channels) and M216 (16 channels).

The only differences are as follows:

1. References in the manual to "6 Frequency" and "14 Frequency" may be considered as "8 Frequency" and "16 Frequency" when servicing M208 or M216 models respectively.
2. M206 and M214 model numbers end with the suffix "AK", whereas M208 and M216 model numbers end with the suffix "BK." For example,

D33LRA77A5AK
D33LRA77A5BK

Radius M206 VHF 25 Watt 6 Frequency Model
Radius M208 VHF 25 Watt 8 Frequency Model

3. Current versions of the Radius Radio Service Software will support the earlier M206/M214 models as well as the later M208/M216 models.

