
USE THIS PROCEDURE TO GAIN ACCESS TO THE PROGRAMMING MODE WHEN PASSWORD HAS BEEN LOST.



WITH POWER APPLIED, SHORT PINS 1 & 3 OF J2 THEN POWER DOWN. POWER UP & REMOUE SHORT. FINALLY POWER DOWN THEN REAPPLY POWER. AT THIS TIME ALL PARAMETERS WILL BE AT DEFAULT. USER MEMORY IS NOT ERASED.