

**INSTRUCTIONS
FOR
AC OUTLET STRIP
OPTION AC01**

(FOR MASTR® II STATIONS)

TABLE OF CONTENTS

	<u>Page</u>
DESCRIPTION	1
OUTLINE & SCHEMATIC DIAGRAM	2
INSTALLATION INSTRUCTIONS	3

DESCRIPTION

The AC OUTLET STRIP Kit contains three Dual AC outlets mounted in a slim metal housing with power cord. The outlet strip comes with necessary hardware to mount in a Desk Mate or Low Power Vertical Mount Cabinet as shown in the Installation Instructions 19D417519.

#8-32 X 3/8 LG. (6 PLACES)

J1-19B209560PI
DISCARD HDW.
SUPPLIED

OUTLET HOUSING
19C320893PI

J2-19B209560PI
DISCARD HDW.
SUPPLIED

J3-19B209560PI
DISCARD HDW.
SUPPLIED

#6-32 X 3/8 LG.
NUT & L' WASHER


CABLE CLAMP 19B215165P3
MT. WITH NUT SUPPLIED

W1

P1

19A134567PI

(PART OF W1)




1. TERMINATE WITH 198209260P101.
2. TERMINATE WITH 198209268P4.
3. TERMINATE WITH 198209268P4 BOTH ENDS.
4. TERMINATE WITH 198209260P4.

(19B226211, Rev. 2)


2

DESK MATE CABINET



DESK MATE CABINET
AC OUTLET STRIP

(19D417519, Rev. 2)



VERTICAL MOUNT CABINET AC OUTLET STRIP

(19D417519, Rev. 2)