

## GENERAL:

This revision outlines changes that have occurred since the printing of your instruction manual. Use this information to correct your manual.

## INSTRUCTION MANUAL AFFECTED:

68P81094E30-O

Power Supply Service Manual

## REVISION DETAILS:

1. This revision is providing a schematic diagram and updated parts list for the TRN7582A Low Voltage Disconnect Hardware. Add this information to your service manual after page 5-23 which is located behind the Mechanical Diagrams and Schematics Tab.

