

Open MTS2000.exe using Hex Workshop.

Use the replace command to look for the following hex strings, and then replace them with the provided strings. Make sure you are searching for hex values.

RX Lower Limit / TX TA Lower Limit

935.0125 = 9428BB37

Change to

926.0000 = 80A33137

Replace command should report changes in two places

TX RPT Upper Limit

901.9875 = AC3CC335

Change to

903.0000 = C0AFD235

Replace command should report changes in one place

Save your work (making a backup copy when prompted is recommended), then close Hex Workshop. Open your MTS software, and confirm that you can now enter frequencies within the Ham band without the software flagging them as invalid. If you can, then you're all set! If not, delete your existing MTS2000.exe, then rename the extension of your MTS2000.bak file that you created to .exe, then try again.