



DATAFILE BULLETIN

FILE UNDER: RECEIVERS
 ER-42-A thru H

BULLETIN NO: 1086-11

DATE: March 1972

EQUIPMENT: 406-470 MHz MASTR Professional Receivers
 Models 4ER42E10-33, F10-27, G10-33, H10-27.

PURPOSE: 19A116203P2 AUDIO PA TRANSISTORS REPLACED BY 19A116741P1

FACTORY SOLUTION:	<u>Model Number</u>	<u>Revision</u>
	19E500881G1,3,5,7 (Chassis & RF Assembly)	K
	19E500881G2,4,6,8 " " " "	L

This revision changed the Audio PA transistors Q410 and Q411 from a 19A116203P2 to a 19A116741P1.

FIELD SOLUTION: Make this revision in the field if the Audio PA transistors have to be replaced for any reason. New mounting hardware is supplied with the new 19A116741P1 transistors.

1. Replace Q410 and Q411 with the new transistors.
2. Stamp or mark the unit with the appropriate revision letter listed above.

ORDERING INFO:	<u>Qty</u>	<u>Symbol</u>	<u>GE Part No.</u>	<u>Description</u>
	2	Q410 & Q411	19A116741P1	Transistor, Silicon NPN.