

Motorola VPN1013A Power Supply

(Extracted from the MCX1000 Service Manual)

